




Straight Tension Fabric Display



1 Connect tubes of the frame (there are number labels on tubes)



2 Wrap up the frames with the graphic from top to bottom and zip up, then put them on the metal base



3 Put the light clip on the top of display and fix it with screw, then connect the light and the clip